Simmons-Boardman Publishing Corporation

RAILWAY Track and Structures

Volume 65 January-December 1969

General Article Index

(*) Illustrated article
(A) What's the answer?
(E) Editorial
(F) For your information
(L) Letter to the editor

American Railway Bridge & Building Assn.:
Election of officers, *Oct 22
American Railway Engineering Association:
Creates special committee on concrete ties, Nov 45
President Wilson cites changes, *Mar 21
Report of March convention, *Apr 16
Armco Steel Corp.:
Prefabricated steel buildings, *Aug 25
Association of American Railroads:
Distributes ballots on track inspection, Dec 40
Atchison, Topeka & Santa Fe:
An approach to the spotting problem, *Sept 36
Uses unusual track construction, *Aug 26

Ballast:
Clean all or just shoulders (A), Aug 43
Machine cleans shoulders, *Jan 20
N&W maintains shoulder ballast with on/off-track machine, *Dec 20
Bangor & Aroostook:
Erects prefab building on flat car, *Aug 25
Bethlehem Steel Corp.:
Panelized turnouts for track construction, *Apr 25
Branch lines:
Are tracks being neglected? (E), Dec 8
Bridges:
B&B records (A), Sept 61
Changing bridge ties (A), Aug 41
Checking clearances (A), June 31
Concerete caps used on timber bridges, *Aug 21
Concrete trestle ties, Sept 17R
CRI&P adopts special fastening, *July 21
Economical bridge forces (A), June 37
Housing B&B gangs (A), Nov 35
Hurricane Camile acts on prestressed concrete bridge, *Oct 14
How they are rated, *May 27
Inspection requires experience, *Dec 25
Market for glulam timbers (E), May 8
Milwaukee uses glulam bridge timbers, *May 22
Obtaining full bearing under shoes (A), Sept 64
Posting piles and framing bents (A), Dec 35
Prefab panels for bridge renewals, Sept 18R
Removing rusty bolts from trestles (A), Dec 34
Salvaging bridge timbers (A), Nov 39
Selection of pile hammers (A), July 37
Southern rebuilds hurricane-destroyed bridge in 10 days, *Nov 20
Strengthening girders under traffic (A), Oct 35
Thermo Tube keeps subsoil stable in permafrost, *Nov 28
Union RR installs crossover on viaduct, *May 24
What to look for in steel bridges, *Dec 26
When to weld or bolt members (A), Mar 61
Buildings:
Application of fiberglass materials (A), May 32
Prefab erected on flat car, *Aug 25

Canadian National:
Develops 100-mph track-recording car, *Nov 44
Now laying heated welded rails, *Dec 22
Canadian Pacific:
Now laying heated welded rails, *Dec 22
Chesapeake & Ohio/Baltimore & Ohio:
Main-line test of concrete crossties, *Jan 22
Chicago, Burlington & Quincy:
Flood preparations pay off, *June 18
Works skeletonizing machine in close quarters, *July 26
Chicago, Milwaukee, St. Paul & Pacific:
Has a tough winter, *Aug 20
Uses glulam timbers on bridge, *May 22
Clearances:
Checking of structures (A), June 31
Clinchfield:
Anchors tunnel roof with rock bolts, *June 28
Concrete and Concrete Work:
AREA creates special committee on concrete ties, Nov 45
Concrete caps on timber bridges, *Aug 21
Concrete-tie test may settle arguments (E), Jan 8
Concrete ties gain favor in Mexico, *Dec 16
Effect of Hurricane Camile on prestressed-concrete bridge, *Oct 14
Trestle ties, Sept 17R
Cranes:
Capacities of on/off-track (A), Apr 37
Keeping them busy (A), July 29
On-track crane adapted to brush cutting, *Mar 30
Crossings:
Construction and maintenance of road crossings, Sept 5R
Is maintenance 100% mechanized?, Sept 4R
Culverts:
Culvert acts like a bridge, *Sept 34
Threading pipe through (A), Mar 58
Curves:
Checking clearances (A), June 31
Different maintenance with CWR (A), Feb 29
When to transpose rail (A), Apr 31

Derailments:
Extinguishing tank car fires (A), Feb 31
Have fostered a new business (E), Feb 8
Mechanization for clearing track, Sept 4R
Pinpointing the problem (E), May 8
Railroads getting a bad press (E), Apr 8
Study problem before passing legislation (E), June 8
Drainage:
At road crossings, Sept 7R
Culvert acts like a bridge, *Sept 34

Electronic Data Processing:
Its effect on foremen, roadmasters and other engineering officers, Sept 14R
Employees:
Adjusting force for vacation (A), Aug 39
Communications with management, Sept 21R
Economical bridge force (A), June 37
Effect of electronic data processing, Sept 14R
Housing of B&B gangs (A), Nov 35
Lack of starts new business (E), Feb 8
Manufacturers size up operator problem, *Mar 24
M/W officers say new type of operator is needed, *Mar 27
More supervision needed (L), Mar 68
Need better communications (E), Aug 8
Need trained operators (L), May 45
Operator problem—What's the cost? (E), Mar 8
Training operators and mechanics, Sept 4R
Transportation for gangs, Sept 2R
Union president discusses operator problem, *Mar 28
Erie Lackawanna:
Saves manpower with anchor applicator, *Sept 38

Fairmont Railway Motors, Inc.:
Chain-saw brush cutter, *Mar 30
W114 Series A Hydraulic Tie Shear, *Mar 32
"Plate-Boy" tie-plate machine, *Sept 40
Model W23-D Ballast Maintenance Car, *Sept 42
Fences:
Is maintenance 100% mechanized?, Sept 4R
Floods:
Hurricane Camile hits L&N, *Oct 14
Preparations pay off on Burlington, *June 18
Washed-out track effects bridge restoration, *Nov 23
Frogs:
IC develops new welding equipment, *Nov 26

Great Northern:
Has worst winter, *Aug 19
Junior Foreman unit eliminates foreman on tampers, *Nov 24

Herbicides:
Directory of manufacturers and products, *Feb 16
Huck Manufacturing Co.:
Bridge bolts, *July 21

Illinois Central:
New welding equipment speeds frog maintenance, *Nov 26
Tries Fairmont's hydraulic tie shear, *Mar 32
Inspection:
Australia gets ultrasonic testing bus (F), *Sept 74
B&B records (A), Sept 61
Bridge inspection requires experience, *Dec 25
CNR develops 100-mph track-recording car (F), Nov 44
In track inspection 100% mechanized?, Sept 4R
Penn Central develops high-speed TRACON car, *Oct 20
Track inspection ordered in Illinois, *June 27
Track in tunnels (A), July 30

Jackson Vibrators, Inc.:
Jackson Model 4000 on/off-track tamper, *Sept 36

Maine Central:
Has four-day snowstorm, *Aug 17
Maintenance of Way:
Are practices up to date? (E), Sept 8
Are branch and yard tracks being neglected? (E) Dec 8
At hump end of yards (A), June 39
Canadian roads now laying heated rails, *Dec 22
Curve maintenance with CWR (A), Feb 29
Divisional vs regional tie gangs (E), Aug 8
Highway crossing maintenance, Sept 5R
How much more money needed? (E), July 8
Importance of precision maintenance, Sept 11R
Machine cleans shoulder ballast, *Jan 20
Make note of trouble spots now (E), Mar 8
Modern maintenance organization, Sept 8R
N&W maintains shoulder ballast with on/off-track machine, *Dec 20
Outlook for 1969, *Jan 15
Practices on British Railways, *May 18
Surfacing behind tie gang (A), Oct 39

UP uses new tamper-liner, *Feb 18
Unloading welded rail (A), Sept 55
Mannix International, Inc.:
New machine cleans ballast shoulders, *Jan 20
Mechanization:
Older men must accept new techniques (E), Feb 8
Missouri Pacific:
Lays CWR in busy yard, *July 18

National Railways of Mexico:
Concrete ties gain favor in Mexico, *Dec 16
New Lines:
Tough going on N&W, *July 14
Nordberg Manufacturing Co.:
Improved Sacrifier-Inserter, *Jan 17
Norfolk & Western:
Maintains shoulder ballast with on/off-track machine, *Dec 20
New line gives problems, *July 14
Northern Pacific:
Has tough winter, *Aug 16
Northwestern Motor Division:
Chain-saw type brush cutter, *Mar 30

Penn Central:
Uses modified tie-renewal machine, *Jan 17
Piles:
Protecting from marine borers (A), Apr 36
Selection of pile hammers (A), July 37
WP protects with special wrapping, *Apr 26
When to post (A), Dec 35
Pipe:
Installing large corrugated (A), Nov 31

Rail:
Are you lubricating efficiently?, *Sept 32
Australia gets ultrasonic testing bus, *Sept 74
Hi-Cant plates as weapon against shelly rails, *Feb 16
Limits of deflection (A), Feb 32
Manganese alloy on British Railways, *May 18
Use of alloy rails in turnouts (A), Nov 41
When to remove shelly rails (A), July 29
When to transpose on curves (A), Apr 31
Year outlook for 1969, *Jan 15
Rail Laying:
Are we 100% mechanized?, Sept. 3R
Distributing tie plates (A), Dec 38
Don't try changing gang organization (E), June 8
Plugging spike holes when transposing (A), Sept 63
Saves manpower with anchor applicator, *Sept 38
Tamping hanging ties (A), Sept 62
Tie-plug installation (A), Oct 38
Unloading material (A), Oct 35
Railway Engineering-Maintenance Suppliers Assn.:
Assn.:
Elects new officers, Apr 41
REMSA gets new executive-secretary, Feb 36
Railway Maintenance Corp.:
Datamatic tamper-liner, *Mar 31
Universal AnchorMaster on Erie Lackawanna, *Sept 38
Railway Products Co.:
Universal Track Machine, *Dec 20
Rail Welding:
Thermit is a tradename (L), May 44
Roadmasters' & M/W Assn.:
Election of officers, *Oct 22
Meeting in September, *Oct 18
Royce Kershaw Co.:
Switch Skeletonizer, *July 26

Safety:
Federal role in setting standards, *Oct 21
How expensive will federal standards be? (E), Nov 8
Safety bill will bring basic changes (E), Dec 8
Study problem before passing legislation (E), June 8
Track inspection ordered in Illinois, *June 27
Who knows the most about it? (E), Sept 8
Will railroads set track standards? (E), Oct 8
St. Louis-San Francisco:
Concrete caps on timber bridges, *Aug 21
Soo Line:
Hard hit with snow, *Aug 18
Southern:
Rebuilds hurricane-destroyed bridge in 10 days, *Nov 20
Southern Pacific:
Trouble at Potrero Hill tunnel, *Jan 25
Supervision:
Don't interfere with rail-gang organization (E), June 8
Supervisor candidates in short supply (E), July 8
Supervisor's role in public relations (A), May 31
Surfacing and Lining:
Are we 100% mechanized?, Sept 3R
Behind tie gang (A), Oct 39
Importance of precision maintenance, Sept 11R
Junior Foreman unit increases output, *Nov 24
Limiting factors in raising track (A), Nov 38
Need for engineers' stakes (A), Feb 27
Outlook for 1969, *Jan 15
UP uses new tamper-liner, *Feb 18
UP uses RMC Datamatic tamper-liner, *Mar 31

Tamper, Inc.:
Junior Foreman effects savings on GN, *Nov 24
Thermo-Dynamics, Inc.:
Thermo Tubes keep subsoil stable in permafrost, *Nov 28
Ties:
Are renewals 100% mechanized?, Sept. 3R
At road crossings, Sept 6R
Best method of disposing of old ties, *Apr 14
Concrete-tie test may settle arguments (E), Jan 8
Concrete ties gain favor in Mexico, *Dec 16
Disposing of old ties in towns (A), Dec 36
Fastenings for concrete ties (L), Jan 41
IC uses Fairmont's hydraulic tie shear, *Mar 32
Installing in sequence (A), May 36
Main-line test of concrete ties on C&O/B&O, *Jan 22
Prestressed-concrete on British Railways, *May 19
Reducing mechanical wear (A), Apr 29
Reducing renewal costs in yards (A), May 37
Regional vs divisional gangs (E), Aug 8
Will machines solve disposal problem? (E), Oct 8
Year outlook, *Jan 15
Track:
Guided roadway for air-cushion vehicle, *June 23
How expensive will federal standards be? (E), Nov 8
Limiting factors in raising (A), Nov 38
Make notes of trouble spots now (E), Mar 8
New type of structure sought (E), Apr 8
Railroad president discusses standards, *Oct 18
Santa Fe to develop high-speed roadbed, *Oct 26
Santa Fe uses unusual construction methods, *Aug 26
Special problems in building BART track, *June 24
Undercuts track along station platforms, *July 26
Union RR installs crossover on viaduct, *May 24
Will railroads set standards? (E), Oct 8
Trestles:
Removing rusty bolts (A), Dec 34
Tunnels:
Checking clearances (A), June 31
Need for cleaning lining (A), June 40
Roofs anchored with rock bolts, *June 28
Trouble at SP's Potrero Hill, *Jan 25
Turnouts:
Panelized for track construction, *Apr 25
Use of alloy rails (A), Nov 41
Welding rails in (A), Mar 50

Union Pacific:
Golden Spike Centennial, *May 26
Tries out RMC Datamatic tamper-liner, *Ma 31
Uses new tamper-liner, *Feb 18
Union Railroad:
Installs crossover on viaduct, *May 24

Weed and Brush Control:
Helicopter boom for herbicide application, *Fe 14
List of herbicide manufacturers and their prod ucts, *Feb 20
On-track crane adapted to brush cutting, *Ma 30
Welded Rail:
At highway crossings, Sept 6R
Canadian roads now laying heated rails, *De 22
In turnouts (A), Mar 50
Laps and gaps when unloading (A), Sept 55
Signs of track buckling (A), Aug 44
Thermit is a tradename (L), May 44
Transposing (A), Dec 31
Used in concrete-crosstie test, *Jan 24
When to use heating machine (A), Dec 37
Welding:
IC develops new equipment to speed frog main tenance, *Nov 26
Western Cullen Division:
On-track crane adapted to brush cutting, *Ma 30
Western Pacific:
Suffocates marine borers with pile wrapping *Apr 26
Winter:
Is snow removal 100% mechanized?, Sept 3R
Last one was bad for snowbelt roads, *Aug 16
Wood preservation:
Protecting piles from marine borers (A), Ap 36
Suffocates marine borers with pile wrapping *Apr 26
Work Equipment:
Better operators are needed (L), May 44
Canadian roads develop rail heater, *Dec 22
Care of flanged-wheel attachments (A), Aug 34
Machinery—Are we 100% mechanized?, Sept 2R
Manufacturers size up operator problem, *Ma 24
Mechanized crossing gang, Sept 7R
M/W officers say new type of operator needed *Mar 27
Needed to solve tie-disposal problem (E), Oc 8
Operator problem—What's the cost? (E), Ma 8
Road modernizes by upgrading (E), Nov 8
Selection of pile hammers (A), July 37
Union president discusses operator problem *Mar 28
Use of flanged-wheel attachments (A), May 34
Yards:
Are tracks being neglected- (E), Dec 8
Is cleaning 100% mechanized?, Sept 4R
Maintenance at hump end (A), June 39
MP lays CWR in busy yard, *July 18
Programming rail renewals (A), Jan 34
Reducing tie-renewal costs (A), May 37

New Products Index

(*) Illustrated Item

Abex Corp.:
Reversible switch-rod clip, *Oct 30
Aerial Platforms:
Ballymore hydraulic, *Sept 68
Up-Mobile hydraulic, June 30
Aeroquip Corp.:
Model 5600 push-pull couplings, *Aug 30
Air Compressors:
Schramm Model 160, *Sept 27
Aldon Co., The:
Grip-Pull car puller, *Sept 72
Allis-Chalmers Corp.:
Backhoe loader Model 918, *Jan 28
Amchem Products, Inc.:
Helicopter boom for herbicide application, *Feb 14
American Hoist & Derrick Co.:
Model 7030 DE locomotive crane, *Mar 44
American Railway Supply Co.:
Flangeway Gard for highway crossings, *Jan 28
Auto Arc Weld Manufacturing Co.:
Auto Arc 4000 wire feeders, *Nov 26

Backhoe Loader, *Jan 28
Ballast Cleaning:
Mannix Shoulder Ballast Cleaner, *Jan 20
Ballast Regulator:
Fairmont W23 Ballast Maintenance Car, *Sept 30, *Sept 42
Kershaw Rotary Scarifier, *Mar 44
Matisa Model 250, *Mar 37

Plasser USP-3000 Hydraulic unit, *Sept 70
Ballymore Co.:
Portable hydraulic-lift platform, *Sept 67
Bantam Division:
T-626 Rail-Roader truck crane, *Sept 30
Bethlehem Steel Corp.:
Panelized turnouts, *Apr 25
Brunton Corp.:
Porta-Loader Model 4612 WP, *June 30
Brush Cutters:
Kershaw Brush Kutter unit, *Mar 48, *Sept 28
Mower attachment for tractor, *Nov 30
Buffalo Weaving & Belting Co.:
Lifting slings, *Dec 28
Bumping Posts:,
Holly Engineering "Hydro-Bumper", *Sept 70

Car Pullers:
Aldon Grip-Pull unit, *Sept 72
Caterpillar Tractor Co.:
Model 627 wheel scraper, *Feb 26
Model 920 wheel loader, *Apr 28
930 Wheel Loader, *Sept 29
Threaded-insert kits for stripped threads, *Oct 30
Chicago Railway Equipment Division:
"Pandrol" fastening for wood ties, *Sept 28
CF&I Steel Corp.:
Hi-Cant plates as weapon against shelly rails, *Feb 16
119-lb rail used on BART, *June 24
Chain Saws:
Carrying case, *June 30
PL-55 Automatic chain saw, *Sept 43
Cox Co., W. T.:
Shunt system for Rail-Road conversion units, *Sept 43
Cranes:
American DieselElectric line, *Mar 44
Drott telescoping boom, June 30
Hy-Rail attachments, *Mar 36
Kershaw Bridge Krane, *Mar 37
Kershaw redesigned bridge crane, *Sept 72
Porta-Loader Model 4612 WP, June 30
R O Products truck crane, *Mar 46
T-626 Rail-Roader truck crane, *Sept 30
Dearborn Chemical Division:
Endcor 500 primer corrosion inhibitor, Oct 30
Devcon Corp.:
Floor Grip non-skid coating, *May 30
Mix-Tube epoxy dispenser, *May 30
Dockboard mechanical ramp, *July 28
Drott Manufacturing Co.:
Hydraulic telescoping boom, June 30

E. F. I., Inc.:
Ultrasonic defect detector, *Dec 28
Engines:
Wisconsin 12-hp diesel, *May 30
Equipment Trailer:
Wisconsin trailer unit, *Mar 28
Equipto:
Safety grating, *Feb 26

Fairmont Railway Motors, Inc.:
Chain-saw type brush cutter, *Mar 30
W114 Series A Hydraulic Tie Shear, *Mar 32
Heavy-duty Hy-Rail attachment, *Mar 36
W113-Series B Dual spike puller, *Mar 42
W23 Series D Ballast Maintenance Car, *Sept 30, *Sept 42
W84 Improved Spike Puller, *Sept 43
W100 Series B Improved hydraulic spike driver, *Sept 67
Flangeway Guard, *Jan 28
Floodlights, outdoors, *Dec 28
Floor Coatings:
"Floor Grip", May 30
Skidproof P-277 Armor Plate, *July 28
Frommelt Industries, Inc.:
Reflective safety tape, *Feb 26

Gerwick Co., Ben C.:
Prestressed ties used on BART, *June 24
Graphic Sciences, Inc.:
Telephone printer, *Dec 28

Herbicides:
Tandex broad spectrum, *Aug 31
Highway Signal:
RACO Advance Warning sign, *Aug 31
Hopper-car unloading doors, *Sept 31
Hose Products Division:
Swivel joint for hydraulic hose, *Nov 30
Hydraulics:
Charger portable power plant, *Sept 66
Control valves, *Jan 28
Model NF-50 filter, *Nov 30
Push-Pull Aeroquip couplings, *Aug 30
Stratoflex non-conducting fittings, *Sept 30
Swivel joint for hoses, *Nov 30

Insulated Joints:
3M Co. unit, *Mar 42
International-Harvester Co.:
Hough H-90E Payloader, *Mar 48

Jackson Products:
Jackson Bump Caps, *Sept 72
Jackson Vibrators, Inc.:
Jackson 5000 System tamper, *Sept 31
Jackson 4000 On/off-track tamper, *Sept 36
Model 2300 combination tamper, *Sept 72
Jacksonville Blow Pipe Co.:
Montgomery Tie Destroyer, *Aug 30, *Sept 29

Kershaw Manufacturing Co.:
Bridge Krane, *Mar 37, *Sept 72
Brush Kutter, *Mar 48, *Sept 28
Rotary Scarifier, *Mar 42
Switch Skeletonizer, *Mar 42
Tie Destroyer, *Mar 37, *Sept 66
Koehring Co.:
T-626 Rail-Roader truck crane, *Sept 30
Krautkramer Ultrasonics, Inc.:
Model SZ-65 Ultrasonic rail tester, *Sept 67

Lewis Bolt & Nut Co.:
Sealtite Spring Lock, *Apr 28
Lighting Equipment Division of Sylvania Electric Products, Inc.:
Outdoor floodlights, *Dec 28
Loaders:
Caterpillar Model 920 unit, *Apr 28
Caterpillar Model 930 unit, *Sept 29
Hough H-90E Payloader, *Mar 48
Taco Richardson Snow thrower attachment, *Nov 30

Machinery, Defect detector, *Dec 28
Mannix International, Inc.:
Heavy-duty boom for Winch Car, *May 30
New loader system for Multi-purpose machine, *Sept 68
Self-propelled Shoulder Ballast Cleaner, *Jan 20
Matisa Equipment Corp.:
ADM-5 Numerical Analyzer for Trackfax car, *Sept 27
Model 250 Ballast Working machine, *Mar 37
Metal Strain Gauge, *Sept 31
Miller Electric Manufacturing Co.:
Trailblazer welding machines, *Nov 26
Motorola Communication & Electronics, Inc.:
HT-220 Handie-Talkie radio, *Apr 28

Niagara Chemical Division:
Tandex herbicide, *Aug 31
Nordberg Manufacturing Co.:
Improved tie Scarifier-Inserter, *Jan 17
Improved Tie Handler, *Mar 36
Northwestern Motor Division:
Chain-saw type brush cutter, *Mar 30

Ocean Coatings, Ltd.:
Non-Flam fire-resistant bridge coating, *Oct 30
Osmose Wood Preserving Co.:
Pile-Gard protects piling on WP, *Apr 26

Parker Hannifin Corp.:
Low-pressure hydraulic control valves, *Jan 28
Swivel joint for hydraulic hose, *Nov 30
Plasser American Corp.:
06-16 Universal tamper, *Feb 18
Universal Switch tamper 2W75-SC, *Sept 70
USP 3000-C Universal Ballast Regulator, *Sept 70

Quaker State Railroad Sales Co.:
Model 160 Schramm compressor, *Sept 27

Racine Hydraulics, Inc.:
Plate-Boy machine, *Sept 30, *Sept 40
Radio:
Motorola HT-220 Handie-Talkie, *Apr 28
Rail Anchors:
"Pandrol" for wood ties, *Sept 28
RMC Universal AnchorMaster, *Sept 38
Rail Grease Texaco EP, Apr 28
Rail-Guide Wheels:
Fairmont Hy-Rail Series 4072 for cranes, *Mar 36
Railroad Accessories Corp.:
Highway warning signal, *Aug 31
Improved tie borer, *Mar 36
Rails Co., The:
Flexiclips used on BART, *June 24
TAB 900-2 switch heater, *Aug 32
Railway Maintenance Corp.:
Datamatic tamper-liner on UP, *Mar 31
Refinements to Auto-Spiker, Dec 28
Universal AnchorMaster, *Sept 38
Railway Products Co., division of Marman Group, Inc.:
Universal Track Machine, *Dec 20
Railway Track-Work Co.:
Improved grapple head "Wood Chuck", *Sept 27
Ranco Industrial Products Corp.:
F-157-FP Kon-Krete Fast Patch, *Oct 30
P-277 Armor Plate floor coating, *July 28
R-39 Shield-Tite roof patching kits, *Aug 32
R-40 Roof Mortar, *July 28
Remington Arms Co., Inc.:
Carrying case for SL-9 chain saw, *June 30
Flexible shafts for power tools, *Feb 26
PL-55 Automatic chain saw, *Sept 43
Rite-Hite Corp.:
Mechanical Railcar Ramps, *July 28
Roofing Repairs:
R-39 Shield-Tite Patching Kits, *Aug 32
R-40 Roof Mortar, *July 28
R O Products, Inc.:
RC-120 truck crane, *Mar 46
Royce Kershaw Co.:
Switch Skeletonizer, *July 26
Russell, Burdsall & Ward Bolt & Nut Co.:
Vibresist locking fastener, *July 28

Safety Grating, *Feb 26
Safety Tape, *Feb 26
Schroeder Brothers Corp.:
Model NF-50 hydraulic filters, *Nov 30
Scrapers:
Cat 627 Wheel Scraper, *Feb 26
Scratch Gage Division:
Scratch Gage, *Sept 31
Shafts, Flexible, *Feb 26
Slings, Lifting, *Dec 28
Snow Throwers:
Taco Richardson attachment for loaders, *Nov 30
Sperry Rail Service:
New ultrasonic system for detector car, June 30
Spike Puller:
Improved Fairmont W113-B unit, *Mar 42
Improved Fairmont W84-G unit, *Sept 43
Spiking Machines:
Improved Fairmont W100-B, *Sept 67
Refinements to Auto-Spiker, Dec 28
Spring Locks:
Sealtite Spring Lock, *Mar 28
Stratoflex, Inc.:
Non-conductive fittings for hydraulic hose, *Sept 30
Switch Heaters:
Sno-Gard gas-fired heaters, *Sept 28
TAB 900-2 hot-air heater, *Aug 32
Switch Undercutter:
Kershaw unit, *Mar 42

Taco Industries, Inc.:
Richardson Snow Thrower, *Nov 30
Tamper, Inc.:
Junior Foreman, *Sept 28, *Nov 24
Telephone printer, *Dec 28
Templeton, Kenly & Co.:
"Charger" portable hydraulic power systems, *Sept 66
Texaco, Inc.:
Grease EP for rail lubricators, Apr 28
Thermo-Dynamics, Inc.
Thermo Tube, *Nov 28
3M Co.:
Insulated rail joint, *Mar 42
Tie Borer, *Mar 36
Tie Destroyer:
Montgomery machine, *Aug 30, *Sept 29
New Kershaw unit, *Mar 37, *Sept 66
Tie Handlers:
Grapple head for RTW unit, *Sept 27
Improved Nordberg unit, *Mar 36
Tie Renewals:
Modified Nordberg Scarifier-Inserter, *Jan 17
Racine's Plate Boy rail lifter, *Sept 30, *Sept 40
Tie Shear:
Fairmont W114-Series A hydraulic, *Mar 33
Tie Tampers:
Jackson Model 2300 combination, *Sept 72
Jackson Model 4000 on/off-track, *Sept 36
Jackson Model 5000 System, *Sept 31
Junior Foreman attachment, *Sept 28, *Nov 24
Plasser 06-16 Universal, *Feb 18
Plasser Universal 2W75-SC, *Sept 29
RMC Datamatic, *Mar 31
Track Inspection:
ADM Analyzer for Trackfax car, *Sept 27
Track Liners:
Plasser 06-16 Universal, *Feb 18
RMC Datamatic, *Mar 31
2C Company:
Rotary-action brush mower, *Nov 30

Undercutting equipment:
Improved Mannix Winch Cart, *May 30
Kershaw Switch undercutter, *Mar 42
Loader system for Multi-Purpose unit, *Sept 68
Up-Mobile Co., The:
Hydraulic aerial platform, *June 30

Vale Enterprises, Ltd.:
Alfex "Colorite" field rail weld, Mar 46
Vapor Corp.:
Sno Gard gas-fired switch heater, *Sept 28
Vibresist locking fastener, *July 28

Weed Burner, three burner, *Sept 43
Welding Rail:
Alfex "Calorite" field welds, Mar 46
IC develops new equipment, *Nov 26
Western Cullen Division:
On-track crane adapted to brush cutting, *Mar 30
Weyerhaeuser Co.:
Glulam timbers, *May 22
Wisconsin Motors:
De-noised diesel engines, *May 30
Wisconsin Trailer Co.:
Tilting equipment trailer, *Apr 28
Woolery Machine Co.:
New three-burner weed burner, *Sept 43

Index to Authors

(*) Illustrated Article

Bell, R. A., Nov 38, Nov 41, Dec 36
Bellinger, L. M., Mar 68
Bertel, D. J., Mar 59
Biggar, T. L., Feb 27, Mar 54, Nov 41
Blanchard, L. C., *Mar 34
Blasingame, J. W., May 36
Bober, H., Nov 39
Boggs, G. B., Apr 29
Bohn, E. P., May 32
Bonner, G. T., May 36
Borst, H. V., Nov 41
Bowman, J. R., Apr 34
Brakensiek, W. E., Jan 36
Bryant, N. D., *Dec 26
Butland, A. N., *May 18

Campbell, F. C., Sept 61
Cannon, W. C., Feb 27
Chambers, J. W., Apr 37
Clark, H., Mar 60
Cleary, E. A., May 44
Corey, W., Aug 37
Crespo, M. J., Jan 31
Crotty, H., *Mar 28
Cummings, E. M., Apr 29

Daniels, D. D., Sept 2R
Danks, A. C., May 32, July 38
Davidson, J. W., Mar 61
Davis, C. D., Apr 33
Dennis, R. E., Sept 5R
Deppler, J. H., May 44
DeValle, Joel W., Jan 41, *Dec 25
Donovan, L. E., Dec 37
Drunsic, W. J., Sept 11R
Dwinnell, W. B., Feb 29

Erhardt, R. D., June 31
Erquiaga, V. R., Aug 34

Fellin, E. E., May 34
Fortney, E. O., May 37
Freeman, L. D., Apr 31

Garland, E. F., July 39
Garland, R. G., Dec 31
Gearhart, G. W., Feb 31
George, L. L., Jan 38
Gerrety, T. F., *Sept 32
Gill, W. J., July 31
Glass, J. T., May 31
Goforth, J. A., June 40
Green, L. W., Mar 50, May 36
Greenlee, J. G., June 32

Haight, C. E. R., Feb 30
Harris, L. C., Sept 18R
Hilton, T. G., May 31
Hoadley, D. E., June 32
Hobbs, J. C., Sept 21R
Holmberg, Ake, Jan 41
Hudson, R. T., Sept 55
Huntsman, W. J., Mar 58

Jacobson, M. A., Nov 35
Jensen, O. H., June 36
Jones, A. C., Sept 17R
Jordan, C. D., Sept 65

Kannowski, K., July 29
Kellogg, H. W., Mar 53
Kemper, R. J., Sept 60
Kessner, H. J., Feb 28
Kieckers, E. W., July 37
Koehler, M. L., *May 27

Laird, W. E., Sept 63
Lawson, L. G., June 44
Leftwich, H. R., Oct 30
Lenzen, L. B., Dec 38
Lingle, T. N., Nov 34
Lloyd, W. H., Oct 30
Low, A. C., Jr., Oct 38
Lowman, H. W., Oct 40
Lynch, J. F., Sept 8R

Masforroll, L., Jan 29
Miller, R. H., Apr 29
Mitchell, D. N., Oct 35

Monoghan, A. E., Mar 54
Moser, C. A., Dec 34
Mullins, J. R., May 48

Nutt, B. L., July 30
Nutt, R. O., Sept 14R
Nyland, B. W., Jan 29

Parker, B. H., July 31
Phelps, C. E. Sr., Sept 64

Ridgeway, J. J., Apr 39
Rigdon, G. M., Aug 39
Ripple, E. D., Mar 62
Rosamond, T. R., May 28
Rougas, M., Feb 32

Salmon, J. M., *June 28
Schifalaqua, M., Oct 38
Schmitz, J. F., Nov 31
Schneider, W. M., Oct 39
Simmons, R. G., Apr 35
Simon, J. J., Aug 44
Smith, D. E., Apr 30
Stanford, C. L., July 36
Starling, S. L., June 37
Stephenson, C. H., July 29
Stone, H. A., Aug 36
Storer, J. W., Apr 37
Stumm, W. H., Aug 39

Tharp, W. M., Jan 34
Thomas, D. D., Dec 35

Vines, H. L., Nov 38
Vito, N. J., June 39, Dec 31
Vosseller, M. E., June 31

Wachter, C. E., Aug 42
Wang, A. B., Nov 34
Warner, Fred, Jan 35
Watson, E., Aug 41
White, R. D., Sept 62
Whitham, W. C., Oct 40
Williamson, H. M., Jan 25
Wilson, H. E., *Mar 21
Worley, D. D., Mar 56

Yarbro, J. L., May 32

Structur